

Product Change Notice

Overview

Alpha Data is committed to the long-term supply of products where it is viable to do so. The products listed below have not been manufactured for over 5 years and are now deemed obsolete.

While there are no direct replacements, please contact sales@alpha-data.com for more information on alternatives.

Product(s) Affected:

All variants of the products listed below are now obsolete.

| | |
|---|---------------------------------|
| ADM-XRC-1472 (AD00100) | AMS-VME (AD01136) |
| Alpha Node (AD00101) | AMS-CMC (AD01137) |
| Alpha Node Front Panel (AD00102) | XRM-ADC-ADS2 (AD01140) |
| Alpha Node Power Distribution (AD00103) | XRM-CCIR(VIDEO-IO) (AD01142) |
| Alpha DC-DC Converter (AD00104) | Quad-PMC-Backplane (AD01143) |
| ADM-XRC-IIL (AD01100) | XRM-HLINK-DUAL (AD01144) |
| ADC-PMC-64 (AD01101) | XRM-SCSI (AD01145) |
| ADM-XRC-II (AD01102) | XRM-DDR-C1 (AD01146) |
| ADM-A2D (AD01104) | XRM-HD-SDI (AD01150) |
| ADM-XPL (AD01106) | ADC-VXS (AD01156) |
| XRM-DDR (AD01108) | XRT-5-LX50 (AD01157) |
| XRM-MDR (AD01109) | XRM-DVI-I (AD01166) |
| XRM-PRO-DEBUG (AD01111) | XRM-DVB-SDI (AD01167) |
| XRM-PRO-DEBUG2 (AD01112) | ADC-EMC (AD01168) |
| ADP-RC2050 (AD01113) | ADM-AMC-5A2 (AD01172) |
| XRM-RAPID IO (AD01114) | XRM-SDRAM-C1 (AD01173) |
| XRM-ZBT (AD01115) | XRM-DA-1 (AD01177) |
| ADP-XRC-N (AD01116) | XRM-FCN-C1 (AD01180) |
| ADM-AUDIO-CC (AD01117) | XRM-ADC-D2-DC (AD01181) |
| ADP-XRC-EMP (AD01118) | ADM-XRC-5T3 (AD01184) |
| ADS-LIU-LMIS (AD01119) | ADM-ARC-3 (AD01187) |
| ADM-XP (AD01120) | XRM-CLNK-ADV (AD01188) |
| ADP-XPI (AD01122) | ADM-XRC-5T2-ADV (AD01189) |
| XRM-CLINK (AD01123) | ADM-XRC-5T2-ADV2 (AD01192) |
| ADP-DRC-II (AD01124) | AD-XIM-FCN (AD01194) |
| XRM-HLNK2 (AD01126) | XRM-DVI-D-RX (AD01195) |
| ADP-WRC-II (AD01127) | ADM-XRC-5T2-ADV-CC-T8 (AD01197) |
| ADP-XPI (AD01131) | XRM-ADC-D6-AC (AD01199) |
| AD-LIP (AD01132) | XRM-CLINK-H264 (AD01203) |
| ADC-PMCe (AD01133) | XRM-CLINK-H264 (AD01205) |
| XRM-RS422 (AD01134) | XRM-OPT-x12 (AD01212) |
| XRM-FCN (AD01135) | XRM-ADC-D8 (AD01216) |


Product Change Notice

Products Affected, Continued

| | |
|--------------------------------|------------------------------|
| AD-XMC-BACKPLANE (AD01223) | ADC-VME-XMC-10G (AD01293) |
| AD-XMC-BACKPLANE-TA1 (AD01228) | XMC-II-Eth-Adaptor (AD01295) |
| ADC-VPX3-GIGE (AD01234) | XRM-NANO-IO146-C2 (AD01296) |
| AD-CLINK-CONV-C (AD01236) | ADT-CPC6-XMC01 (AD01297) |
| AD-SATA-ADPT-C (AD01240) | AD-Breakout-7Z2-C1 (AD01300) |
| ADM-XRC-5T-RH (AD01243) | ADM-PCIE-KU3-X8 (AD01301) |
| XRM-10G-QSFP (AD01244) | AD-BREAKOUT-6TGE (AD01306) |
| XRM-ADC-Q8 (AD01250) | ADM-PCIE-8V3 (AD01308) |
| XRM-DAC-D4-DC-1G (AD01251) | AD-XRM-EXTENDER (AD01312) |
| ADA-VPX3-6T1 (AD01258) | XRM EXTENDER2 (AD01314) |
| ADA-VPX3-7K1 (AD01259) | XRM-DA2-100-DC (AD01316) |
| ADA-VPX3-7V1 (AD01260) | ADC-PCIE-DA3 (AD01334) |
| ADM-XRC-6TGEL (AD01262) | AD-SAS-LOOP (AD01343) |
| FMC-OPT (AD01263) | FMC-CLINK-MINI-RX (AD01348) |
| FMC-10GT (AD01266) | SHA-Debug (AD01349) |
| ADM-VPX3-6T-ADV4 (AD01269) | AD-Breakout-7Z4 (AD01351) |
| ADC-VPX6-GIGE (AD01271) | ADM-XRC-5T1-GT6 (AD01352) |
| ADC-VPX6-BYPASS (AD01272) | FMC-IPASS-SFP6 (AD01359) |
| ADM-V73-7K (AD01274) | XRM2-VIDEO-CAPTURE (AD01383) |
| ADC-XMC-BREAKOUT (AD01276) | AD-SATA-FIREFLY (AD01390) |
| ADM-PCIE-7V3-X16 (AD01278) | FMC-COAXPRESS/R7 (AD01402) |
| ADC-CPC6-XMC01 (AD01280) | FMC-COAXPRESS/T7 (AD01403) |
| ADM-VPX3-CTL1 (AD01282) | ADM-XRC-6T1A (AD01405) |
| AD-Breakout-7Z2 (AD01283) | |

Impact on Form, Fit or Function: n/a**Effective Date of Change:**

The listed products are already obsolete and have been out of production for more than 5 years. Further orders will not be accepted.

| | |
|--|----------------------|
| Director:  | Date: 20-Mar-2026 |
| Quality Representative: <i>Dianne Angus</i> | Date: 20 Mar 2026 |